Detailed Report

Date of Submission : 30-09-2026 11:09

UPPER_JURALA - 220KV tripped at ***28-09-2026 05:57*** and restored at ***28-09-2026 08:27***

Summary of Event (घटना का सारांश)	:	PJHES is Operating with 220KV Double bus with Bus Coupler. During Antecedent conditions, Elements connected to Bus-I are Raichur Feeder-I and Elements Connected to Bus-II are Raichur Feeder-II& Unit#4 MTR back charging. 220KV Jurala station dead on 28.09.2026 @05:57 HRS due to no voltage from 220KV Raichur end. The same was informed to LDC and as per the instructions of LDC the jurala#1&2 feeder was charged from our end on 28/09/2026 @ 07:22 Hrs. 220KV Raichur -1&2 feeders idle charged from other end at 28.09.2026 @ 07:23Hrs, Station Changed over to Raichur -1& 2 feeders at 28.09.2027 @ 08:27Hrs, fully

station restored normally.

Time and Date of the event (घटना का समय और दिनांक) : 28-09-2026 05:57

Name of the Substation/Generating Station/Pooling Station affected (Along with Voltage level) : : UPPER_JURALA - 220KV

Event Category (श्रेणी के साथ इवेंट प्रकार) : GD - 1

Location/Control Area (स्थान/नियंत्रण क्षेत्र) : TELANGANA

Configuration of Bus (HV/LV) . Along with details of Bus split Operation (if any) :

Bus Configuration Type :

Bus Coupler Status : NA

Bus 1 Connected Elements	Bus 2 Connected Elements	Bus 3 Connected Elements	Bus 4 Connected Elements

Station Connectivity / SLD during antecedent :

Weather Conditions :

Elements under outage prior to the event :

Other Information (Antecedent Cnditions) : na

Renewable Energy Trip : False

Details of SPS Operation (if any): : False

Reason of tripping :

Load and Generation Loss (लोड और जेनरेशन हानि) :

Total Generation Loss (MW)	Total Load Loss(MW)
0 MW	0 MW

Duration of interruption (रुकावट की अवधि) :

Details of Equipment Failure (if any during the event): :

Equipment Type	Equipment Make

List of elements tripped during the event : 1.

Station Connectivity/SLD during the event :

Analysis of the event : Jurala Station is changed over towards Telangana AT 07: 22hrs. 220kV Raichur_KA-RTPS 1&2 Normalized at

07:23Hrs. 220kV Raichur_KA-Upper Jurala 1&2 charged at 08:27Hrs. station fully resotred normally.

Protection / Operational Issues observed :

Restoration Details :

DR Time synchronization issues observed (सुरक्षा/ प्रचालन समस्या) : False

Remedial Measures Taken (सुधारात्मक सुझाव) : NA

Relay/PLCC Operation Details :

Control Panel Anunciation	:	NA
Main I Relay Indications	:	NA
Main II Relay Indications	:	NA
Other Relay Indications	:	NA
PLCC Counter Increment I/T	:	
PLCC Counter Increment D/T	:	
Fault Current Value (kAmp)	:	None
LA Counter	:	
Remarks	:	
Attachments	:	