Detailed Report

Date of Submission : 17-09-2026 11:18

KARWAR - 220KV tripped at ***15-09-2026 11:14*** and restored at ***15-09-2026 12:22***

Summary of Event (घटना का सारांश)	:	MAIN SUPPLY FAILURE FROM KADRA END DUE TO BUS DEAD AT KADRA END, NO TRIPPINGS AT 220kV KARWAR (OUR) END
Time and Date of the event (घटना का समय और दिनांक)	:	15-09-2026 11:14
Name of the Substation/Generating Station/Pooling Station affected (Along with Voltage level) :	:	KARWAR - 220KV
Event Category (श्रेणी के साथ इवेंट प्रकार)	:	GD - 1
Location/Control Area (स्थान/नियंत्रण क्षेत्र)	:	KARNATAKA
Configuration of Bus (HV/LV) . Along with details of Bus split Operation (if any)	:	

Bus Configuration Type :

Bus Coupler Status : NA

Bus 1 Connected Elements	Bus 2 Connected Elements	Bus 3 Connected Elements	Bus 4 Connected Elements

Station Connectivity / SLD during antecedent	:	
Weather Conditions	:	

Elements under outage prior to the event :

Other Information (Antecedent Cnditions) :

Renewable Energy Trip : False

Details of SPS Operation (if any): : False

Reason of tripping : Others

Other Reason : MAIN SUPPLY FAILURE FROM KADRA END

Load and Generation Loss (लोड और जेनरेशन हानि) :

Total Generation Loss (MW)	Total Load Loss(MW)
0 MW	55.65 MW

Duration of interruption (रुकावट की अवधि) :

Details of Equipment Failure (if any during the event): :

Equipment Type	Equipment Make

List of elements tripped during the event : 1.

Station Connectivity/SLD during the event :

Analysis of the event : MAIN SUPPLY FAILURE FROM KADRA END DUE TO BUS DEAD AT KADRA END, NO TRIPPINGS AT 220kV KARWAR (OUR) END

Protection / Operational Issues observed :

Restoration Details :

DR Time synchronization issues observed (सुरक्षा/ प्रचालन समस्या)	:	False
Remedial Measures Taken (सुधारात्मक सुझाव)	:	
Relay/PLCC Operation Details	:	
Control Panel Anunciation	:	
Main I Relay Indications	:	
Main II Relay Indications	:	
Other Relay Indications	:	
PLCC Counter Increment I/T	:	
PLCC Counter Increment D/T	:	
Fault Current Value (kAmp)	:	None
LA Counter	:	
Remarks	:	MAIN SUPPLY FAILURE FROM KADRA END DUE TO BUS DEAD AT KADRA END, NO TRIPPINGS AT 220kV KARWAR (OUR) END
Attachments	:	