

Detailed Report

Date of Submission : 23-07-2026 11:55

VAJAMANGALA - 220KV tripped at 22-07-2026 16:23 and restored at 23-07-2026 11:53

Summary of Event (घटना का सारांश) :

Time and Date of the event (घटना का समय और दिनांक) : 22-07-2026 16:23

Name of the Substation/Generating Station/Pooling Station affected (Along with Voltage level) : VAJAMANGALA - 220KV

Event Category (श्रेणी के साथ इवेंट प्रकार) : GD - 1

Location/Control Area (स्थान/नियंत्रण क्षेत्र) : KARNATAKA

Configuration of Bus (HV/LV) . Along with details of Bus split Operation (if any) :

Bus Configuration Type : Double Bus with Bus coupler

Bus Coupler Status : NA

Bus 1 Connected Elements	Bus 2 Connected Elements	Bus 3 Connected Elements	Bus 4 Connected Elements
1. 220KV-HOOTAGALLI-VAJAMANGALA-1	1. 220KV-TK_HALLI-VAJAMANGALA-1		

Station Connectivity / SLD during antecedent :

Weather Conditions : Normal

Elements under outage prior to the event : 1. 220KV-TK_HALLI-VAJAMANGALA-1

Other Information (Antecedent Cnditions) : 220KV Vajamangala-TK Halli Line under LC from 23.06.2026

Renewable Energy Trip : False

Details of SPS Operation (if any): : False

Reason of tripping :

Load and Generation Loss (लोड और जेनरेशन हानि) :

Total Generation Loss (MW)	Total Load Loss(MW)
0 MW	0 MW

Duration of interruption (रुकावट की अवधि) :

Details of Equipment Failure (if any during the event): :

Equipment Type	Equipment Make
----------------	----------------

List of elements tripped during the event : 1.

Station Connectivity/SLD during the event :

Analysis of the event :

Protection / Operational Issues observed :

Restoration Details :

DR Time synchronization issues observed (सुरक्षा/प्रचालन समस्या) : False

Remedial Measures Taken :
(सुधारात्मक सुझाव)

Relay/PLCC Operation Details :

Control Panel Anunciation :

Main I Relay Indications :

Main II Relay Indications :

Other Relay Indications :

PLCC Counter Increment I/T :

PLCC Counter Increment D/T :

Fault Current Value (kAmp) : None

LA Counter :

Remarks :

Attachments :